


Corner of the raceway as it enters Tyson Creek. The creek splits into two arms at this point. The right arm (in view) is fish bearing. The silty water (center left) in the photo is from the runoff collected behind the powerhouse (as previously noted, corrective action has been taken).



[Next slide](#)